# TECHNICAL REPORT OF GROUND WATER, GEMS MINERALS, CRUDE OIL INVESTIGATION


# 114 N.T.I.Layout, 1st Block, Sahakaranagar, Bangalore - 560 092. **Karnataka, INDIA**
# 786, 4th Cross Prakruthi Layout, Hennur Bangalore - 560 043. **Karnataka, INDIA**

**V. Kantharaj, M.A., Natural Wealth Explorer**
**Ganga Borwells Proprietor**

Cell : +91 98453 45034
+91 98458 45034
+91 98459 01252
080 6990 0999
v.kantharaj786@gmail.com
kantharajv56@gmail.com


To,
Mr./Mrs. Assistant Executive Engineer
Vidyaranyapura RBNP

Ground water ..... investigation was carried out as per your applicationd / request dated 05-3-2022 on your site land located at P.B. Village Thindlu Taluk Bangalore District..... State ..... on 5-3-22 in order to assess the Ground water potential of the area fo drinking / irrigation / Industrial / Apartment / Commercial / Public Purpose.

1. The area investigated is aslope towards North East
Uneven topography and is covered by Red mixed Soil
Hydrological feature are found to be favorable for Ground Water Extraction. Geology of the area is mark by White & Black mixed Rock

2. TWO ② Borewell points are been pointed out in the surveyed area by the methods of Survey..... **B, C, G, M, S**

3. Location Map






4. From the above observation a Bore Well ..... is recommended/~~not recommended~~ for drilling at Bore Well No. ..... one & Two For 6" / 6.5" to a depth of 800 to 1000 (200 feets below the ground level. Casing Pipe required may be to a depth of ..... 130 to 140 ..... fts. The approximate yield may be ..... 1500 to 2000 G.P.H/ L.P.H./Inches ..... 2" to 3" .....

**Note : This report is valid for only 3 months**

**Although the best site for drilling has been suggested no guarantee of success can be assured.**

**Service Charges Rs.** 2 points

**V. Kantharaj, M.A.**
Natural Wealth Explorer

# TECHNICAL REPORT OF GROUND WATER, GEMS MINERALS, CRUDE OIL INVESTIGATION


# 114 N.T.I.Layout, 1st Block, Sahakaranagar, Bangalore - 560 092. **Karnataka, INDIA**
# 786, 4th Cross Prakruthi Layout, Hennur Bangalore - 560 043. **Karnataka, INDIA**

**V. Kantharaj, M.A.,** Natural Wealth Explorer
Ganga Borwells Proprietor

Cell : +91 98453 45034
+91 98458 45034
+91 98459 01252
080 6990 0999
v.kantharaj786@gmail.com
kantharajv56@gmail.com


To,
Mr./Mrs. Asst Executive Engineer
BBMP 3rd Cross Vidyaranyapura

Ground water ..... investigation was carried out as per your applicationd / request dated 05-3-2022 on your site land located at Near Park Village Thidlu Taluk Gnaneswara Layout District ..... State ..... on 05-3-22 in order to assess the Ground water potential of the area fo drinking / irrigation / Industrial / Apartment / Commercial / Public Purpose.

1. The area investigated is aslope towards North East
Uneven topography and is covered by Red mixed clay soil
Hydrological feature are found to be favorable for Ground Water Extraction. Geology of the area is mark by White Black Mixed Rock

2. one (1) Borewell points are been pointed out in the surveyed area by the methods of Survey B, C, G, M, S

3. Location Map






4. From the above observation a Bore Well ..... is recommended/~~not recommended~~ for drilling at Bore Well No. one (1) For 6" / 6.5" to a depth of 800 to 1000 feets below the ground level. Casing Pipe required may be to a depth of 130 to 140 fts. The approximate yield may be 1500 to 2000 G.P.H/ L.P.H./Inches 2 to 3"

**Note : This report is valid for only 3 months**
**Although the best site for drilling has been suggested no guarantee of success can be assured.**

**Service Charges Rs.** 5000/-

**V. Kantharaj, M.A.**
Natural Wealth Explorer